

PID:	011940905
SD/MU:	-
WO:	-

## PRINCE GEORGE Civic Address: 5521 LAWYER PLACE Legal Description: Lot: 106 District Lot: 1599 Plan: 15792

Service Type	Diameter (mm)	Material	Invert Elev @ Main (m)		ert Elev @ rty Line (m)	Invert Elev @ Service End (m)	Distance Property		stallation Date	
Sanitary	Unknown	Unknown	-	-		-	-		Unknown	
Water	Unknown	Unknown	-	-		-	-		Unknown	
Storm	N/A	-	-	-		-	-	-		
Sanita	ry Service Co	nnection Lo	cation Notes		S	torm Service Con	nection Loc	cation Note	es	
Distance from downstream SAN MH #: Unknown					Distance from downstream STM MH #: N/A					
Distance to upstream SAN MH #: Unknown					Distance to upstream STM MH #: N/A					
			Mis	cellane	ous Utilities					
Power Communications				Cable		Gas				
BC Hydro TELUS				Shaw Cable			FortisBC			
Overhead Service Overhead Service				Overhead Service			Underground Service			
Installation By:	Inknown					Survey Date: 2020-0			2020-09	
				Comr	nents:		·			
Curb Stop is located	d ~0.6m from the	East property line	e of Lot 106. Horse	Shoe Ser	vice to Lot 106 a	and Lot 105.				
Inspection complete	ed 2020-09 as per	Inspection #414	3262.							
						n is for internal us ction and/or inves				
IN										

