

PRINCE GEORGE

Civic Address: 1733 Upland St

Legal Description: Lot: PCL A (PN292) Block: 274 District Lot: 343 Plan: 1268

Service Type	Diameter (mm)	Material	Invert Elev @ Main (m)	Invert Elev @ Property Line (m)	Invert Elev @ Service End (m)	Distance into Property (m)	Installation Date
Sanitary	200	PVC	-	-	-	-	March 2020
Water	20	COPPER	-	-	-	-	Jan 1961
Storm	N/A	-	-	-	-	-	-

Sanitary Service Connection Location Notes	Storm Service Connection Location Notes		
Distance from downstream SAN MH #3170: 48.23m	Distance from downstream STM MH #: N/A		
Distance to upstream SAN MH #3173: 63.29m	Distance to upstream STM MH #: N/A		

Miscellaneous Utilities							
Power Communications		Cable	Gas				
BC Hydro	TELUS	Shaw Cable	FortisBC				
Overhead Service	Overhead Service	Overhead Service	Underground Service				

stallation By: Unknown	Draft Date:	2024-01-12	Survey Date:	2020-03-10
------------------------	-------------	------------	--------------	------------

Comments:

Water Service is ~24.9m South from the North West corner of PCL A. Sanitary Service / Clean Out is ~25.3m South from the North West corner of PCL A.

Services are side by side.

NOT TO SCALE The information contained herein is for internal use only. Not to be relied on unless confirmed by site inspection and/or investigation. 200Ø AC SANITARY 450Ø C STORM ENCUMBRANCE: EPP113720 -24.86 UPLAND LANE PCL A 200Ø CI WATER 350Ø CI WATER SANITARY MAIN SANITARY SERVICE / CLEAN OUT STORM MAIN STORM SERVICE / CLEAN OUT WATER MAIN WATER SERVICE / CURB STOP **ROAD EDGE** FIRE HYDRANT LEAD, VALVE, HYDRANT **ENCUMBRANCE**