

PRINCE GEORGE

Civic Address: 687 IRWIN ST

Legal Description: Lot: Parcel E Block: 24 District Lot: 937 Plan: 752

Service Type	Diameter (mm)	Material	Invert Elev @ Main (m)	Invert Elev @ Property Line (m)	Invert Elev @ Service End (m)	Distance into Property (m)	Installation Date
Sanitary	100	PVC	-	-	-	-	January 1960
Water	19	COPPER	-	-	-	-	January 1960
Storm	N/A	-	-	-	-	-	-

Sanitary Service Connection Location Notes	Storm Service Connection Location Notes		
Distance from downstream SAN MH #2662: 21.67m	Distance from downstream STM MH #: N/A		
Distance to upstream SAN MH #2658: 89.33m	Distance to upstream STM MH #: N/A		

Miscellaneous Utilities								
Power	Communications	Cable	Gas					
BC Hydro	TELUS	Shaw Cable	FortisBC					
Overhead Service	Overhead Service	Overhead Service	Underground Service					

Installation By: Unknown Survey Date: N/A

Comments:

Water Service is ~8.8m from the North East corner of Parcel E. Sanitary Service is ~9.4m from the North East corner of Parcel E.

NOT TO SCALE The information contained herein is for internal use only. Not to be relied on unless confirmed by site inspection and/or investigation.

