Lot Services Sketch



PID:	006566766
BU:	430100
MO.	5021039

Civic Address: 8396 CANTLE DR

Legal Description: Lot: 20 District Lot: 625 Plan: 14430

Service Type	Diameter (mm)	Material	Invert Elev @ Main (m)	Invert Elev @ Property Line (m)	Invert Elev @ Service End (m)	Distance into Property (m)	Installation Date
Sanitary	100	AC	744.09	744.40	744.45	0.36	January 1977
Water	19	COPPER	743.79	744.10	744.38	1.51	January 2021
Storm	N/A	-	-	-	-	-	-

Sanitary Service Connection Location Notes	Storm Service Connection Location Notes		
Distance from downstream SAN MH #4812: 5.02m	Distance from downstream STM MH: N/A		
Distance to upstream SAN MH #4748: 73.92m	Distance to upstream STM MH: N/A		

Miscellaneous Utilities							
Power	Communications	Cable	Gas				
BC Hydro	TELUS	Shaw Cable	FortisBC				
Overhead Service	Overhead Service	Overhead Service	Underground Service				

Installation By: City of Prince George Survey Date: 2021-01-05

Comments:

Sanitary clean out is 1.00m from East property line, water curb stop is next to clean out.

CCTV Inspection #4214676 completed 2021-11-08. Inspection #4139513 completed 2021-01-05.

NOT TO SCALE The information contained herein is for internal use only. Not to be relied on unless confirmed by site inspection and/or investigation.

