



CITY OF
PRINCE GEORGE

Civic Address: 8298 CANTLE DRIVE

Legal Description: Lot: 2 District Lot: 625 Plan: 14430

Lot Services Sketch

| | |
|------|-----------|
| PID: | 012008711 |
| BU: | - |
| WO: | - |

| Service Type | Diameter (mm) | Material | Invert Elev @ Main (m) | Invert Elev @ Property Line (m) | Invert Elev @ Service End (m) | Distance into Property (m) | Installation Date |
|--------------|---------------|----------|------------------------|---------------------------------|-------------------------------|----------------------------|-------------------|
| Sanitary | 100 | AC | Unknown | Unknown | Unknown | Unknown | January 1977 |
| Water | 19 | COPPER | Unknown | Unknown | Unknown | Unknown | January 1977 |
| Storm | N/A | - | - | - | - | - | - |

| Sanitary Service Connection Location Notes | Storm Service Connection Location Notes |
|--|---|
| Distance from downstream SAN MH #4751: 5.43m | Distance from downstream STM MH #: N/A |
| Distance to upstream SAN MH #4755: 96.46m | Distance to upstream STM MH #: N/A |

| Miscellaneous Utilities | | | |
|-------------------------|------------------|------------------|---------------------|
| Power | Communications | Cable | Gas |
| BC Hydro | TELUS | Shaw Cable | FortisBC |
| Overhead Service | Overhead Service | Overhead Service | Underground Service |

| | | | |
|---|-----------------------|--------------|------------|
| Installation By: | City of Prince George | Survey Date: | 2021-08-16 |
| Comments: | | | |
| Locate Inspection completed 2021-08-16 as per inspection #4207899. CCTV Completed 2021-08-11 as per inspection #4207512. | | | |
| Curb Stop is ~1.4m from the Southern property line of Lot 2. Clean Out is ~2.1m from the Southern property line of Lot 2. | | | |

**NOT TO SCALE The information contained herein is for internal use only.
Not to be relied on unless confirmed by site inspection and/or investigation.**

