



CITY OF
PRINCE GEORGE

Civic Address: 8360 CORRAL ROAD

Legal Description: Lot: 3 District Lot: 625 Plan: 13646

Lot Services Sketch

| | |
|------|-----------|
| PID: | 012331244 |
| BU: | 411197 |
| WO: | 5019638 |

| Service Type | Diameter (mm) | Material | Invert Elev @ Main (m) | Invert Elev @ Property Line (m) | Invert Elev @ Service End (m) | Distance into Property (m) | Installation Date |
|--------------|---------------|----------|------------------------|---------------------------------|-------------------------------|----------------------------|-------------------|
| Sanitary | 100 | PVC | 743.51m | - | - | - | September 2020 |
| Water | 19 | COPPER | - | - | - | - | January 1977 |
| Storm | N/A | - | - | - | - | - | - |

| Sanitary Service Connection Location Notes | Storm Service Connection Location Notes |
|-----------------------------------------------|-----------------------------------------|
| Distance from downstream SAN MH #4746: 94.19m | Distance from downstream STM MH #: N/A |
| Distance to upstream SAN MH #5627: 2.38m | Distance to upstream STM MH #: N/A |

| Miscellaneous Utilities | | | |
|-------------------------|------------------|------------------|---------------------|
| Power | Communications | Cable | Gas |
| BC Hydro | TELUS | Shaw Cable | FortisBC |
| Overhead Service | Overhead Service | Overhead Service | Underground Service |

| | | | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|--------------|------------|
| Installation By: | City of Prince George | Survey Date: | 2020-09-16 |
| Comments: | | | |
| Curb Stop is ~1.7m from East property line of Lot 3. Clean Out is ~42.6m from East property line of Lot 3. Services are located on each side of Lot 3. | | | |
| Inspection completed 2022-05-05 as per Inspection #4227722 | | | |

NOT TO SCALE The information contained herein is for internal use only.
Not to be relied on unless confirmed by site inspection and/or investigation.

